

INFLATOR SCS SILVER REPLACEMENT

SCS Silver Inflator (with metal buttons) is out of line.

That's why SEACSUB has decided to supply Inflator assy code S77452 and Power Inflator code S77453 till the stock ends.

Once the stock runs out, we'll replace them with the Standard version (plastic buttons) codes S75054 e 0480466, currently inline.

SCS SILVER CURRENT PART	SCS STANDARD REPLACEMENT
Inflator Assy code S77452	Inflator Assy code S75054
Power Inflator code S77453	Power Inflator code 0480481

Maintenance kit: 0480481 Service kit SCS Standard Inflator can be used to service Silver version. After serious evaluation, we have decided to include the inflation button assembly (plastic) into the kit.

It's the safest way to service this Inflator.

So the technician has two options:

- 1) Replace the inflation button, so that the Inflator will have one plastic and one metal button. The button are interchangeable, since the body is the same.
- 2) Get and replace the deflation button also (plastic version)



WARNING !

All service and repair procedures on Seac products should be performed by qualified Seac Service Technicians at authorized Seac Dealers and Service Centers.